



## AK893 GAUZY AGENT GLASS COAT

High quality product developed to enhance, repair, and achieve extremely realistic transparent glass-like finishes on clear plastic parts. Simply dip and let dry for a few minutes. Clean excess around the edges to achieve a uniform layer. For best results, allow product to dry in a dust-free environment. This product,



when applied to clear plastic, will result in a realistic glass-like appearance on parts like clear plastic cockpit canopies or other clear parts.



Clean the piece to remove all dust and fingerprints. We can use tweezers or fix the piece temporarily for better handling. It is important to work on dust-free ambient.



Dip the piece for a few seconds making sure the liquid reaches all crevices.



Take out the piece letting it drain and making sure there are no bubbles.



Dry the excess leaning it over a paper cloth or similar making sure the product does not accumulate too much in one area.



During the drying time it is recommended to leave it to dry protected to avoid the ambient dust deposits over it. If we find ourselves with that problem we must clean the piece with alcohol and repeat the process again.

### Notes:

The drying time may vary depending on environmental conditions, although it can be manipulated after 30 minutes it is advisable to let it dry for several hours. A good planning of your work and avoiding the rush will help.

Keep in mind that when drying, the product has good adhesion and the piece can get stuck where we let it dry. So you have to be careful to move it from time to time during the first minutes of drying or left in a place so that the bearing surface is minimal.

